

CITY OF VINELAND
DEPARTMENTAL REQUEST FOR PUBLIC BIDDING


1. NATURE OF REQUEST: Masonry Wall Repairs - Boilers 7, 8, & 9 Building

2. ENGINEER'S ESTIMATE: \$ 25,000.00
(If Engineer's Estimate has been prepared by anyone other than the person signing this form, please attach a copy of said Engineer's Estimate.)

3. AMOUNT BUDGETED FOR THIS REQUESTED ITEM: \$ 25,000.00

4. BUDGETED ITEM: YES NO
(If no, is it an ordinance authorized material, service or supply?)

YES NO ORDINANCE NO.: _____



(B) Please identify the page number and line item appropriation sub-account:

Budget Page No. _____ Account No. 002-0-55-90-9001-2-9022000 E341C

5. Check here if:

Federal Funds State Funds

UEZ Funds Davis Bacon Requirements

(If any of the above are checked, the project must be monitored by the department for compliance with prevailing wage rate policy and procedures.)

6. Date to be Advertised: October 11, 2016

7. Date to be Received: October 25, 2016

8. Date to be Awarded: November 7, 2016

9. Special Conditions or Instructions: Please waive requirements for Bid Bond and Consent of Surety.

A pre-bid meeting will be held at H.M. Down Station at 10:00 AM on Friday, October 14, 2016.

10. The following must be attached:

Summary of Project

Specifications


Plans (if applicable)

Bidders Mailing List (with emails of the vendor)

11. Specifications Prepared by: M.L. Puri, Principal Engineer Ext. 4249
(NAME, TITLE AND EXTENSION NUMBER)

12. Approved by:


SIGNATURE (DIRECTOR, DEPARTMENT HEAD, SUPERVISOR)

Send copies to:
Purchasing Department
Business Administration 

Handwritten notes:
9/21/16
John
9/21/16
9/21/16

MASONRY WALL REPAIRS – BOILERS 7, 8, & 9 BUILDING

VMEU H.M. DOWN STATION

PROJECT SUMMARY

This project involves services by an outside contractor for masonry repair of the north and south walls and parapets of boilers #7, 8 & 9 building. This building which was built in stages during the 1950's is showing early signs of damage from water leakage. The proposed repairs will replace the failing section of the parapet and seal the coping stone and wall joints to maintain the structural integrity of the walls. This will help minimize future maintenance/repair costs.

Prepared By:

Mohan Puri
Principal Engineer